



ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂಖ್ಯೆ: ಸಕಾಅ: ಲೋಇ: ನಂ.2:ಉವಿ:ಸು.ಪ್ರ.ಪ: /443  
2022-23

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರವರ ಕಛೇರಿ  
ಲೋಇ, ನಂ.2, ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು  
ದಿನಾಂಕ: 27-07-2022

ರವರಿಗೆ:-

MANAGING TRUSTEE,  
C.S.Education Trust,  
No.79, Srinivasa Complex,  
1<sup>st</sup> Main Road, Sheshadripuram,  
Bengaluru-560 020.

ಮಾನ್ಯರೇ,

ವಿಷಯ:- C.S.Education Trust ರವರ Vishwa Vidyapeeth, Sy.No.3/1 & 3/3,  
Honnenahalli, Doddaballapur Road, Yelahanka Taluk, Bengaluru-  
560 064, ವಿಳಾಸದಲ್ಲಿರುವ ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ  
ಬಗ್ಗೆ.

- ಉಲ್ಲೇಖ:-
1. ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019,  
ದಿನಾಂಕ:06.05.2022
  2. ತಮ್ಮ ಮನವಿ ದಿನಾಂಕ:- 16.06.2022
  3. ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ:- ಸಕಾಅ: ಲೋಇ: ನಂ.2:ಉವಿ:ಸು.ಪ್ರ.ಪ:439  
2022-23 ದಿನಾಂಕ:- 26.06.2022

\*\*\*\*

ಮೇಲಿನ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, C.S.Education Trust ರವರ Vishwa Vidyapeeth, Sy.No.3/1 & 3/3,  
Honnenahalli, Doddaballapur Road, Yelahanka Taluk, Bengaluru-560 064, ವಿಳಾಸದಲ್ಲಿರುವ ಶೈಕ್ಷಣಿಕ ಕಟ್ಟಡದ  
ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು ಉಲ್ಲೇಖ (2) ರ ಪತ್ರದಲ್ಲಿ ಕೋರಿರುತ್ತೀರಿ.

ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019 ದಿನಾಂಕ: 06.05.2022 ರಲ್ಲಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,  
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ರವರು ಶಾಲಾ/ಕಾಲೇಜು ಕಟ್ಟಡಗಳನ್ನು ಪರಿಶೀಲಿಸಿ Structural stability ನಿರಾಕ್ಷೇಪಣಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು  
ಅಧಿಕಾರ ಪ್ರತ್ಯಾಯೋಜನೆಗೊಳಿಸಿ ಸೂಚಿಸಿರುವುದರಿಂದ ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡಕ್ಕೆ ಈ ಕೆಳಕಂಡಂತೆ ಪರದಿ ನೀಡಲಾಗಿದೆ.

ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡದ ಪರಿವೀಕ್ಷಣೆಯನ್ನು ಕೆಳಗೆ ಸಹಿ ಮಾಡಿದ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ದಿನಾಂಕ:- 15.07.2022 ರಂದು  
ಈ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ತಂಡದೊಂದಿಗೆ, Vishwa Vidyapeeth, Sy.No.3/1 & 3/3, Honnenahalli, Doddaballapur Road,  
Yelahanka Taluk, Bengaluru-560 064, ವಿಳಾಸದಲ್ಲಿರುವ ಕಟ್ಟಡವನ್ನು ಸದರಿ ವಿದ್ಯಾಸಂಸ್ಥೆ ಯವರ ನೋಂದಾಯಿತ ಸ್ವತಃ  
ಇಂಜಿನಿಯರ್ ರವರ ಉಪಸ್ಥಿತಿಯಲ್ಲಿ ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿದ್ದು, ಕಟ್ಟಡವನ್ನು ತಳಮಹಡಿ, ನೆಲಮಹಡಿ ಮತ್ತು ಎರಡು ಮೇಲ್ಮಹಡಿಗಳನ್ನು  
ಹೊಂದಿರುವಂತೆ ನಿರ್ಮಿಸಲಾಗಿದ್ದು, ಕಟ್ಟಡದಲ್ಲಿ ಆಡಳಿತ ವಿಭಾಗ, ತರಗತಿ ಕೋಣೆಗಳು, ಪ್ರಯೋಗಾಲಯಗಳು, ಮೆಟ್ಟಿಲುಕೋಣೆಗಳು ಮತ್ತು  
ಶೌಚಾಲಯ ಒಳಗೊಂಡಂತೆ 2018 ರಲ್ಲಿ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ. ಕಟ್ಟಡದ ದೃಢತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ: ಲೋಇ 59  
ಬಿಇಡಿ 2019 ದಿನಾಂಕ: 06.05.2022 ರಲ್ಲಿ ಕಡ್ಡಾಯವಾಗಿ 2 ರೀತಿಯ Non-destructive test ಗಳನ್ನು ಕೈಗೊಂಡು ಫಲಿತಾಂಶವನ್ನು  
ಪರಿಶೀಲಿಸಿ ಕಟ್ಟಡದ ಸ್ಥಿತಿಗತಿಯ ಬಗ್ಗೆ ಸೂಕ್ತವಾದ ಷರಾ ಹಾಗೂ ಶಿಫಾರಸ್ಸಿನೊಂದಿಗೆ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಸೂಚಿಸಿರುವುದರಿಂದ ಸಂಸ್ಥೆಯವರ  
ಸಹಯೋಗದೊಂದಿಗೆ 2 ರೀತಿಯ Non-destructive test ಗಳನ್ನು NABL Accredited Lab ಮುಖಾಂತರ CIVIL EXPERTS,  
Consultants and Testing Center, Bengaluru, ರವರ ವತಿಯಿಂದ ಕೈಗೊಳ್ಳಲಾಗಿದ್ದು, ಸದರಿ ಪರಿಶೀಲನೆಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ  
ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ ಮತ್ತು ಫಲಿತಾಂಶಗಳು ತೃಪ್ತಿಕರವಾಗಿರುತ್ತದೆ ಎಂದು ವರದಿಯಲ್ಲಿ ತಿಳಿಸಲಾಗಿರುತ್ತದೆ.

*Sheantha S. Reman*

Principal

Vishwa Vidyapeeth

Honnenahalli, Yelahanka Hobli  
Bengaluru North Taluk - 560 064

*[Signature]*  
Director  
Vishwa Vidyapeeth

Honnenahalli, Yelahanka Hobli  
Bengaluru North Taluk - 560 064

**TRANSLATION TYPED COPY-1**  
**Department of Public Works**

No: AEE:PWD: No.2:ND:S.C:/443  
2022-23

Assistant Executive Engineer's Office  
PWD, No.2, North Sub Division, Bangalore  
Date: 27-07-2022

To,  
Managing Trustee,  
C.S. Education Trust  
No.79, Srinivasa Complex,  
1<sup>st</sup> Main Road, Sheshadripuram,  
Bengaluru-560 020.

Dear

Subject:- C.S. Education Trust to Vishwa Vidyapeeth, Sy No.3/1 & 3/3,  
Honnenahalli, Doddaballapur Road, Yelahanka Taluk,  
Bengaluru-560064. Issuing safety certificate for the  
educational building.

Reference :- 1. Government Circular No: PWD 59 BED 2019, dated: 06-05-2022  
2. Date of their appeal:- 16-06-2022  
3. This office, Letter No: AEE:PWD: No.2:ND:S.C:/443

Whereas the mentioned above, C.S. Education Trust to Vishwa Vidyapeeth, Sy No.3/1 & 3/3, Honnenahalli, Doddaballapur Road, Yelahanka Taluk, Bengaluru-560064, has requested to issue the safety certificate for the educational building at the address of Reference (2).

Government Circular No: PWD 59 B E D 2019 dated: 06-05-2022 Assistant Executive Engineer, Public Works Department has been delegated authority to inspect school and college buildings and issue Structural Stability No Objection Certificate, so the following report has been issued for the proposed building.

Inspection of the proposed building by the undersigned Assistant Executive Engineer, dated:- 15-07-2022 with sub division technical team condemned a building at Vishwa Vidyapeeth, Sy. No/1 & 3/3, Honnenahalli, doddaballapur Road, Yelahanka Taluk, Bengaluru-560064, Inspected in the presence of the Registered: Psychical Engineer of the said Institution, the building is constructed with Basement Floor, ground Floor, and two upper floors, the building will be constructed in 2018 including administrative department, classrooms, laboratories, stairwells and toilets. Regarding the strength of the building, Government Circular No: PWD 59 BED 2019 dated:06-05-2022 mandatory to carry out 2 types of Non-destructive tests and check the results to issue a certificate with suitable para and recommendation about the condition of the building. Conducted by NABL Accredited Lab and CIVIL EXPERTS, Consultants and Testing Center, Bengaluru, the report states that in the said test, the building is found to be of good quality and the results are satisfactory.

*Shantha Rave*  
**Principal**

**Vishwa Vidyapeeth**  
**Honnenahalli, Yelahanka Hobli**  
**Bengaluru North Taluk - 560 064**

Director  
Vishwa Vidyapeeth  
Honnenahalli, Yelahanka Hobli  
Bengaluru North Taluk - 560 064

## TRANSLATION TYPED COPY-2

### The organization has submitted the following documents

- Building plan approved by Singanayakanahalli Gram Panchayat.
- Suguna engineering consultancy to Certificate for SUB SURFACE INVESTIGATION CERTIFICATE.
- Specs Consulting Civil Engineers, BCC/BL-3.6/SE.0195/2021-22, Bangalore issued building CERTIFICATE FOR COMPLETED STRUCTURAL DESIGN WORK AS PER STRUCTURAL SAFETY REQUIREMENTS.
- Yelavarthy Jagadish Raju issued FORM FOR CERTIFICATE FOR COMPLETED WORK BY BUILDER /CONSTRUCTOR CERTIFICATE.
- Yelavarthy Jagadish Raju issued FORM FOR CERTIFICATE FOR SUPERVISION OF WORK CERTIFICATE.
- Specs Consulting Civil Engineers, BCC/BL-3.6/SE.0195/2021-22, Bangalore issued FORM FOR COMPLETION CERTIFICATE AFFIDAVIT .
- Tenure deeds issued by Singanayakanahalli Gram Panchayat.
- Para:- The enumerators are instructed to carry out the following works in the building on priority.
- Staircase steps to be ensured to be skid resistant by suitable means.
- General periodical maintenance for over all building.
- Water Proofing work to be taken up in terrace floor with proper drainage arrangements with all necessary Safety Measures.
- No Further Floor to be constructed and modifications or alterations must be with proper Technical Advice and Guidance.

Further, as per the Government circular referred to (1), the fee fixed for issue of Building Safety Certificates is a total of Rs.5000/- (Rupees Five Thousand Only) to Bank of Baroda in the name of D.D, Assistant Executive Engineer, PWD No.2, North Sub-Division, Bangalore in the name of D.D.No.066538, dated: 27-07-2022 paid.

Regarding the Non-Structural Elements (Infrastructural facilities) of the proposed building, an objection letter should be obtained from the inspection team consisting of civil engineer, health officer, revenue officer, psychologist, fire officer, local body officials and Fire safety certificate should Chief Firefighter be obtained from the officer.

Verify all the documents issued by the said institution, inspect the building and prepare the necessary examination report at C.S. Education Trust to Vishwa Vidyapeeth, Sy No.3/1 & 3/3, Honnenahalli, Doddaballapur Road, Yelahanka Taluk, Bengaluru-560064, West side CBSE BLOCK, No objection letter has been given that BLOCK educational building is structurally Stable .

S.R. RAVIKUMAR, B.Com.,LLB.,  
ADVOCATE & NOTARY PUBLIC  
GOVT. OF INDIA

49/A, 5th 'A' Cross, Subbanna Garden.

Principal  
Vishwa Vidyapeeth  
Honnenahalli, Yelahanka Hobli  
Bengaluru North Taluk - 560 064

Your's Faithfulness,  
Assistant Executive Engineer,  
PWD, No.2, North Sub-Division ,  
Bangalore

Director  
Vishwa Vidyapeeth  
Honnenahalli, Yelahanka Hobli  
Bengaluru North Taluk - 560 064

Vishwa Vidyapeeth  
Honnenahalli, Yelahanka Hobli  
Bengaluru North Taluk - 560 064

Priyanka

Health Revenue